





1/19



2/19




Figure 1E




Figure 1F

3/19

16

16




Figure 2A

Figure 2B




Fig. 2C

Fig. 2D

Fig 3A

16 →




Fig 3B

16 →





Fig 3C

16 →



5/19




Figure 4

6/19




Fig. 5A




Fig. 9A

7/19




Fig 5B

8/19




Figure 6



9/19





Fig. 7






Figure 8B

12/19






Figure 9B









FIG. 10D



Foot Stirrup  
w/ Connecting Ring

Figure 11






FIG. 13A




FIG. 12




Figure 13B

19/19




Figure 14